

Release Notes

CoreLogic Database Update July 2023

Summary of Changes

80 new Item Operations added for the July Database Update

Database Updates

- Standard monthly material price update
- New Items Include: Vanity Tops, Wood Reducer Strip, Girder Tie, H-Clips, Reception Desk, Detach Trim, Detach Cabinets & Wooden Steep Roof Charge.

Claims Construction Bulletin

 To keep our clients informed of current market trends, CoreLogic[®] has curated a monthly bulletin of trending cost variations for various loss types by regions within the U.S.

Item Image Updates

- 38 new images were added for the July database update.
- 1771 total images are currently present in the database, covering 3004 specific line items.

-	*		• •		*			*													*		*	*		*		*	•	
		*				*		*	-	-							+		+									+		
	•		• •						-					*				-												-
		As	sen	nbiy	/ Up	pàq	tes																		+	-				
	*	-(Fi	xes c	ind L	Jpd	ates	5 - 7	sse	mb	lie	s)	-		-	-		*		-	-	÷	-	-			-	-	•	*	-
				Non	e			0													0					0				
	٠			141		-	1	~	*		. 44			-								-						*		1
7	5	2																1			5							1		1
	÷	De	esk /	٩dju	iste	er U	pd	ate	S										-	+					-	-	τ.			
	-	(Fi	xes c	ind L	Jpd	ates	5 – <i>L</i>) esk	(Ac	djus	ster) -			-	•				•		-		-		-			•	
-				-					-		-		-	-		-														-
				Non	e																									
											-	-		-	-					 -		-				-				
							-		-	-										-		-						1		



corelogic.com

New items added for the July 2023 Database Update

-	CAB - Vanity	Vanity Top, Cultured Marble, Single Bowl, per LF	Rem/Reset	LF
	CAB - Vanity	Vanity Top, Cultured Marble, Single Bowl, per LF	Reset	LF
	CAB - Vanity	Vanity Top, Cultured Marble, Single Bowl, per LF	Remove	LF
-	CAB - Vanity	Vanity Top, Cultured Marble, Single Bowl, per LF	Replace	LF
	CAB - Vanity	Vanity Top, Cultured Marble, Single Bowl, per LF	Tear Out	LF
	CAB - Vanity	Vanity Top, Cultured Marble, Double Bowl, per LF	Rem/Reset	- LF-
	CAB - Vanity	Vanity Top, Cultured Marble, Double Bowl, per LF	Reset	- LF-
	CAB - Vanity	Vanity Top, Cultured Marble, Double Bowl, per LF	Remove	LF.
	CAB - Vanity	Vanity Top, Cultured Marble, Double Bowl, per LF	Replace	LF
	CAB - Vanity	Vanity Top, Cultured Marble, Double Bowl, per LF	Tear Out	LF
	CLN - Cabinets & Countertops	Vanity Top, Cultured Marble, Single Bowl, per LF	Clean	LF
	CLN - Cabinets & Countertops	Vanity Top, Cultured Marble, Single Bowl, per LF	Clean, Heavy	LF
	CLN - Cabinets & Countertops	Vanity Top, Cultured Marble, Single Bowl, per LF	Clean, Light	LF
	CLN - Cabinets & Countertops	Vanity Top, Cultured Marble, Double Bowl, per LF	Clean	LF
	CLN - Cabinets & Countertops	Vanity Top, Cultured Marble, Double Bowl, per LF	Clean, Heavy	LF
	CLN - Cabinets & Countertops	Vanity Top, Cultured Marble, Double Bowl, per LF	Clean, Light	LF
	MIT - Water Mitigation	Muck Out, Confined Space, During Business Hours	Special	SF
	MIT - Water Mitigation	Muck Out, Confined Space, After Hours	Special	SF
	MIT - Water Mitigation	Muck Out, Heavy, During Business Hours	Special	SF
	MIT - Water Mitigation	Muck Out, Heavy, After Hours	Special	SF
	MIT - Water Mitigation	Muck Out, Heavy, Confined Space, During Business Hours	Special	SF
	MIT - Water Mitigation	Muck Out, Heavy, Confined Space, After Hours	Special	SF
	FRM - Posts & Beams	Girder Tie, 2 Ply, Light Duty	Rem/Reset	EA
	FRM - Posts & Beams	Girder Tie, 2 Ply, Light Duty	Reset	EA
	FRM - Posts & Beams	Girder Tie, 2 Ply, Light Duty	Remove	EA
	FRM - Posts & Beams	Girder Tie, 2 Ply, Light Duty	Replace	EA
	FRM - Posts & Beams	Girder Tie, 2 Ply, Light Duty	Tear Out	EA
	FRM - Posts & Beams	Girder Tie, 3 Ply, Heavy Duty	Rem/Reset	EA
	FRM - Posts & Beams	Girder Tie, 3 Ply, Heavy Duty	Reset	EA
	FRM - Posts & Beams	Girder Tie, 3 Ply, Heavy Duty	Remove	EA
	FRM - Posts & Beams	Girder Tie, 3 Ply, Heavy Duty	Replace	EA
	FRM - Posts & Beams	Girder Tie, 3 Ply, Heavy Duty	Tear Out	EA
	FRM - Sheathing	Sheathing, Roof H-Clips	Special	SF
	FCO - Wood	Wood Reducer Strip, Hardwood	Rem/Reset	LF
	FCO - Wood	Wood Reducer Strip, Hardwood	Reset	LF
	FCO - Wood	Wood Reducer Strip, Hardwood	Remove	LF
	FCO - Wood	Wood Reducer Strip, Hardwood	Replace	LF
	FCO - Wood	Wood Reducer Strip, Hardwood	Tear Out	LF
	FCO - Wood	Wood Reducer Strip, Engineered	Rem/Reset	LF
	FCO - Wood	Wood Reducer Strip, Engineered	Reset	LF
	FCO - Wood	Wood Reducer Strip, Engineered	Remove	LF
	FCO - Wood	Wood Reducer Strip, Engineered	Replace	LF
	FCO - Wood	Wood Reducer Strip, Engineered	Tear Out	LF
	100-0000	mood Neddeer July, Lingineered		



				8	+
MAS - Brick & Block Walls	Beam/Joist Pocket, Top	Special	EA.		
MAS - Brick & Block Walls	Beam/Joist Pocket, Below Top	Special	EA		
CIF - Interior Furnishings	Reception Desk, Good	Rem/Reset	LF		
CIF - Interior Furnishings	Reception Desk, Good	Reset	LF		
CIF - Interior Furnishings	Reception Desk, Good	Remove	LF	2	
CIF - Interior Furnishings	Reception Desk, Good	Replace	LF		
CIF - Interior Furnishings	Reception Desk, Good	Tear Out	LF	7	
CIF - Interior Furnishings	Reception Desk, Very Good	Rem/Reset	LF		
CIF - Interior Furnishings	Reception Desk, Very Good	Reset	- LE-	-	
CIF - Interior Furnishings	Reception Desk, Very Good	Remove	un LFaur		
CIF - Interior Furnishings	Reception Desk, Very Good	Replace	LF	-	
CIF - Interior Furnishings	Reception Desk, Very Good	Tear Out	LF		
CIF - Interior Furnishings	Reception Desk, Excellent	Rem/Reset	LF		
CIF - Interior Furnishings	Reception Desk, Excellent	Reset	LF		
CIF - Interior Furnishings	Reception Desk, Excellent	Remove	LF		
CIF - Interior Furnishings	Reception Desk, Excellent	Replace	LF		
CIF - Interior Furnishings	Reception Desk, Excellent	Tear Out	LF		
CLN - Other	Reception Desk	Clean	LF		
CLN - Other	Reception Desk	Clean, Heavy	LF		
CLN - Other	Reception Desk	Clean, Light	LF		
MIT - Water Mitigation	Detach Trim, After Hours	Special	LF		
MIT - Water Mitigation	Detach Trim, During Business Hours	Special	LF		
MIT - Water Mitigation	Detach Cabinet, Base, After Hours	Special	LF		
MIT - Water Mitigation	Detach Cabinet, Wall, After Hours	Special	LF		
MIT - Water Mitigation	Detach Cabinet, Full Height, After Hours	Special	LF		
MIT - Water Mitigation	Detach Cabinet, Base, During Business Hours	Special	LF		
MIT - Water Mitigation	Detach Cabinet, Wall, During Business Hours	Special	LF		
MIT - Water Mitigation	Detach Cabinet, Full Height, During Business Hours	Special	LF		
RFG - Other	Steep Roof Charge, Wood Roofing, 7/12-9/12	Remove	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, 7/12-9/12	Replace	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, 7/12-9/12	Tear Out	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, 10/12-12/12	Remove	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, 10/12-12/12	Replace	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, 10/12-12/12	Tear Out	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, Greater than 12/12	Remove	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, Greater than 12/12	Replace	SQ		
RFG - Other	Steep Roof Charge, Wood Roofing, Greater than 12/12	Tear Out	SQ		



.....

About CoreLogic

•

÷	-C	ore	Log	gi∈ i	s th	ne le	ead	ing	pro	ovic	ler	ofp	rop	bert	y-ir	nsig	hts	an	d-so	olut	tion	IS, p	oroi	not	es a	a he	ealt	hy			1
	housing market and thriving communities. Through its enhanced property data solutions,																														
•	-			-		-		-				0						ate					-					-	ons	, "	154
																		ousi For	<u> </u>		1.00			1.00						ă.	1
÷				ic.c	· .	1000					u p					0111									pre						3
						*	-					*											-								
÷							-							-		-						÷				-					
							1.0																-		-						
																									-						
		-					-						. *				-						-							×	1

For more information, visit CoreLogic.com.

© 2022 CoreLogic, Inc. All rights reserved. CORELOGIC and the CoreLogic logo are trademarks of CoreLogic, Inc. and/or its subsidiaries. All other trademarks are the property of their respective holders.



corelogic.com